#### 2D Profile Measuring Sensors

# ZG - Smart Profile Sensor

#### The easy way to get your profile

The smart ZG sensor solves ambitious profile measurement applications. An easy and intuitive user interface enables efficient installation, setup and operation. The advanced processing technology is a break-through for the needs of high speed processes. Precise shape measurement is guaranteed on challenging materials and surfaces. A built-in LCD monitor presents the measurement result in real time.

- · Easy to use intuitive user interface
- Live built-in LCD monitor for setup and immediate profile display
- Versatile 18 measurement tools
- Accurate 5 µm resolution
- · Wide profiles up to 70 mm
- · Fast 5 ms sampling time
- Smart powerful PC software for configuration and post-processing (optional)



#### Easy to use

Complex operational procedures are time consuming and costly. The new ZG differentiates from standard products by its usability. The intuitive icon based menu, enables an easy setup and configuration of advanced measurement tasks within 3 steps.



Step 1

Adjust Sensor Head

Check on LCD display



Check results on display



Simple ICON menu

Step 3 Select range

Automatic calculation

# Control with keys

#### Live - built-in LCD monitor

The built-in LCD monitor of the ZG represents an intuitive user interface for easy setup and immediate live feedback of measurement result. This helps to save time for the initial configuration, change of measurement task and reduces the training efforts for personnel. A fine tuning of the settings can be achieved in seconds. The LCD monitor enables to check the measurement result at any time during operation, without the need to connect an external PC. The reaction time for maintenance activities can be short-ened.

#### Versatile - diverse measurement functions

Step

Edge and Width

The ZG can solve advanced measurement tasks. Up to 18 different functions are available to meet the requirements of the applications. They allow to calculate e.g. the width, height, angle or area of the profile. The measurement functions can be selected from the easy to understand icon based user interface on the LCD monitor.

Height





Step from base





Others (Angle, Area, Calc ...)





#### Intelligence inside - automatic adjustment of laser power

Point

In many industrial processes sensors have to deal with difficult or changing materials. In order to avoid time consuming reconfigurations to reliably detect the objects, the sensor by itself has to manage the constraints of the process. The ZG provides an automatic adjustment of the laser power, depending on the surface of the object. The deviation of the reflection, e.g. of different colors can be compensated by increasing or decreasing the laser power to achieve the best result.

Further improvements of the measurement result can be achieved e.g. on shiny surfaces. The reflection level on different parts of the measurement object can be different, which can result in incomplete profiles.

To complement the profile ZG has the capability to take several images and to combine them. The "multi-sensitivity function" allows to adjust the incident light on the different parts of the object and to retrieve a complete shape.

#### Flexible - balance between speed and accuracy



Image with Lo-LD-power

The ZG Smart profile sensor offers different modes of operation, which allows adjusting the sensor behavior to the application requirements. The optimization can be done either towards high speed or high accuracy. For high speed processes the sampling time can be decreased to 5 ms. In the other direction 5 µm accuracy can be achieved.



## Applications

#### Width measurement - car body

- Task: Measure the gap between different parts of the car body
- Industry: Automotive
- Challenge: Changing colours of the objects
- Solution: Automatic Laser power adjustment in ZG
- Key point: Higher accuracy than vision systems



#### Warpage measurement - PCB

- Task: Measure the warpage of a PCB to avoid soldering or connection defects
- Industry: Electronics



# Area measurement - glue bead measurement

- Task: Measure the presence or shape of a glue bead to control the continuous motion of a robot
- Industry: Automotive



#### Position measurement - paper

- Task: Control the position of the paper and check whether there is a drift (meandering)
- Industry: Paper



#### Angle measurement - car seat

- Task: Measure the angle of the car seat
- Industry: Automotive
- Key point: Controller can calculate any angle by defining additional tasks

#### Measuring air-bag notch

- Task: Measure depth and width of an airbag notch
- Industry: Automotive
- Key point: High accuracy

#### **Basic Configuration**

#### Sensor Heads



#### Cable length between Sensor Head and Controller



### **Ordering Information**

#### Sensor Heads

Optical method	Sensing distance		Reso	Model	
	Height direction	Width direction	Height direction	Width direction	
Diffuse reflective	210±30 mm	70 mm	10 µm	70 mm/631 pixels	ZG-WDS70
Diffuse reflective	100±12 mm	22 mm	3 µm	22 mm/631 pixels	ZG-WDS22
Diffuse reflective	50±3 mm	8 mm	1 µm	8 mm/631 pixels	ZG-WDS8T
Regular reflective	20±0.5 mm	3 mm	0.25 µm	3 mm/631 pixels	ZG-WDS3T

#### Sensor Controllers

Appearance	Power supply	Output type	Model
	24 VDC	NPN	ZG-WDC11A*
]		PNP	ZG-WDC41A*

\* Included with Smart Monitor ZG Setup Support Software and USB cable.

#### Accessories (Order separately)

#### Real-time Parallel Unit (for the ZG-WDC-Series)

Appearance	Output type	Model	
	NPN	ZG-RPD11	
	PNP	ZG-RPD41	

#### RS-232 Cable

Connecting device	Model	Qty
For personal computer connection (2 m)	ZS-XRS2	1
For PLC/PT connection (2 m)	ZS-XPT2	1

#### Sensor Head Extension Cable

Name	Model	Qty
3 m Extension Cable	ZG-XC3CR	1
8 m Extension Cable	ZG-XC8CR	1
15 m Extension Cable	ZG-XC15CR	1
25 m Extension Cable	ZG-XC25CR	1
Digital Equalizer (Relay Device)	ZG-XEQ	1
0.2 m Digital Equalizer Connection Cable	ZG-XC02D	1

#### Parallel Mounting Adaptor

Appearance	Model		
	ZS-XPM1	For 1 Unit	
22	ZS-XPM2	For 2 Units or more	

#### Sensor Heads

Item	Model	ZG-WDS70	ZG-WDS22 ZG-WDS8T		ZG-WDS3T			
Optical syst	tem	Diffuse reflective	Diffuse reflective	Regular reflective	Diffuse Regular reflective		Regular reflective	Diffuse reflective
Measure- ment range	Height direction (in standard mode)	210±30 mm	100±12 mm	94±10 mm	50±3 mm	44±2 mm	20±0.5 mm	5.2±0.4 mm
	Width direction	70 mm (typical)	22 mm (typica	22 mm (typical)		8 mm (typical)		3 mm (typical)
Resolution	Height direction <sup>*1</sup>	10 µm	3 µm		1 µm		0.25 μm	
	Width direction	70 mm/631 pixels	22 mm/631 pixels		8 mm/631 pixe	els	3 mm/631 pix	els
Linearity (in the heig	ht direction) *2	±0.5% F.S.						
Temperatur characterist	re tic <sup>*3</sup>	0.1% F.S./°C						
	Туре	Visible semiconductor laser					1	
Light	Wavelength	658 nm					650 nm	
source	Output	5 mW max. output, 1 mW max. exposure (without using optical instruments)					1 mW max.	
	Laser class	Class 2M (JIS C 6802 2005)				Class 2 (JIS C 6802 2005)		
Beam shape (at measure- ment center distance) *4		120 µm×75 mm (typical)	60 μm×45 mm (typical) 30 μm×24 mm (typical)		25 µm×4 mm (typical)			
LED		STANDBY: Lights when laser irradiation preparation is complete (indication color: green) LD_ON: Lights when the laser is irradiating (indication color: green)						
Measureme	ent object	Opaque material						
Ambient light intensity		Incandescent lamp: 1,000 lx max. (light intensity on the receiver surface)						
	Ambient temperature	Operating: 0 to 50°C, Storage: -15 to 60°C (with no icing or condensation)						
E nu dina n	Ambient humidity	Operating and storage: 35 to 85% (with no condensation)						
ment	Degree of protection	IP66 (IEC 60529) IP64 (IEC 6052					529)	
resistance	Vibration resistance (destruction)	10 to 150 Hz with 0.35 mm single amplitude for 80 min each in X, Y and Z directions						
	Shock resistance (destruction)	150 m/s <sup>2</sup> , 3 times each in 6 directions (up/down, right/left, forward/backward)						
Materials Case: Aluminium diecast, Front cover: Glass, Cable insulation: Heat-resistive polyvinyl chloride (PV Connector: Zinc alloy or brass		chloride (PVC),						
Cable length		0.5 m, 2 m						
Minimum be	ending radius	68 mm						
Weight		Approx. 650 g	Approx. 500 g		Approx. 500 g		Approx. 300 g	l
Accessories		Laser Labels (EN, 2 labels).	Ferrite Core (1	). Instruction M	anual			

Note: 1 . Obtained by setting an OMRON standard measurement object at the measurement center distance and determing the average height of the beam line. The conditions are given in the table below. However, satisfactory resolution cannot be attained in strong electromagnetic fields.

		Aver- age No. of Oper- ations	Measurement object		
Model	CCD Mode		Regular reflective	Diffuse reflective	
ZG-WDS70/ WDS22/ WDS8T	Stan- dard mode	16	OMRON standard white alumina ceramic object		
ZG-WDS3T	Stan- dard mode	32	OMRON stan- dard mirrored object	OMRON stan- dard diffuse re- flective object	

2. The tolerance for an ideal straight line obtained by determing the average height of an OMRON standard measurement object for the beam line. The CCD standard models used. Linearity varies depending on the measurement object.

Model	Measurement object			
Model	Regular reflective	Diffuse reflective		
ZG-WDS70/ WDS22/WDS8T	OMRON standard white	alumina ceramic object		
ZG-WDS3T	OMRON standard mir- rored object	OMRON standard dif- fuse reflective object		

3 . A value attained by using an aluminium jig to secure the distance between the Head and the measurement object. The CCD standard mode is used.

4 . Defined as  $1/e^2$  (13.5%) of the center light intensity. This may be influenced when light leakage also exists outside the defined area and the reflectivity of the light around the measurement object is higher than that of measurement object.

#### Sensor Controllers

ltem		Mode	ZG-WDC11A	ZG-WDC41A		
Input/output type			NPN	PNP		
No. of connectable Sensor Heads		sor Heads	1 per Controller			
Measurement cycle <sup>*1</sup>			16 ms (high-precision mode), 8 ms (standard mode), 5 ms (high-speed mode)			
Min. display unit			10 nm			
Display ra	ange		-999.99999 to 999.99999			
Display LEDs		LCD monitor	1.8 inch TFT color LCD (557×234 pixels)			
		LEDs	<ul> <li>Judgment indicators for each task (indication color: orange): T1, T2, T3, T4</li> <li>Laser indicator (indication color: green): LD_ON</li> <li>Zero reset indicator (indication color: green): ZERO</li> <li>Trigger indicators (indication color: green): TRIG</li> </ul>			
		Analog outputs	<ul> <li>Select voltage or current (using the sliding sv</li> <li>Voltage output: -10 to 10 V, output impedan</li> <li>Current output: 4 to 20 mA, maximum load</li> </ul>	vitch on the bottom surface) ice: 40 $\Omega$ resistance: 300 $\Omega$		
		Judgment output (ALL-PASSING/ERROR)	NPN open collector	PNP open collector		
	Input/output	Trigger auxiliary output (ENABLE/GATE)	Residual voltage: 1.2 V max.	Residual voltage: 1.2 V max.		
External	signal lines	Laser stop input (LD-OFF)				
Interface		Zero reset input (ZERO)	ON: 0 V short or 1.5 V max. OFF: Open (leakage current: 0.1 mA max.)	ON: Power supply voltage short or power sup ply voltage -1.5 V min. OFF: Open (leakage current: 0.1 mA max.)		
		Measurement trigger input (TRIG)				
		Bank switching input (BANK A, B)	_			
	Sarial I/O	USB2.0	1 port, full speed (12 Mbps), MINI-B			
	Serial I/O	RS-232C	1 port, 115,200 bps max.			
		No. of setting banks	4			
		Sensitivity adjustment	Multi/auto/fixed			
Main fund	ctions	Measurement items	Height, 2-point Step, 3-point Step, Edge posi four items can be measured simultaneously)	tion, Edge width, Angle/Area Calculation (up to		
		Trigger modes	External trigger/continuous			
		Power supply voltage	21.6 to 26.4 VDC (including ripple current)			
Patinge		Current consumption	0.8 A max.			
Raunys		Insulation resistance	20 M $\Omega$ at 250 V between lead wires and Con	troller case		
		Dielectric strength	1,000 VAC, 50/60 Hz for 1 min between lead	wires and Controller case		
		Ambient temperature	Operating: 0 to 50°C, Storage: -15 to 60°C (v	vith no icing or condenstaion)		
		Ambient humidity	Operating and storage: 35 to 85%			
Environm	ental	Degree of protection	IP20 (IEC 60529)			
Vibration resistance (destruction) Shock resistance (destruction)		Vibration resistance (destruction)	Vibration frequency: 10 to 150 Hz, single amplitude: 0.35 mm, acceleration: 50 m/s <sup>2</sup> , 10 times for 8 min each			
		Shock resistance (destruction)	150 m/s <sup>2</sup> , 3 times each in 6 directions (up/down, right/left, forward/backward)			
Materials			Case: Polycarbonate (PC), Cable insulation: Heat-resistive polyvinyl chloride (PVC)			
Cable length			2 m			
Weight			Approx. 300 g (including cable) (Packed state: Approx. 450 g)			
Accessories			Large Ferrite Core (1), Small Ferrite Core (2), Insulation lock (1), Instruction Manual, Smart Monitor ZG Setup Support Software (CD-ROM) USB Cable (1 m)			

Note: 1 . The image input periode listed here are for fixed/auto sensitivity. The image input period will be longer for multi-sensitivity or other settings. Use the eco monitor in RUN mode to determine the actual image input period.

ALL DIMENSIONS SHOWN ARE IN MILLIMETERS.

To convert millimeters into inches, multiply by 0.03937. To convert grams into ounces, multiply by 0.03527.

Cat. No. Q150-E2-01-X

In the interest of product improvement, specifications are subject to change without notice.